BrightSign®

BrightAuthor:connected Release Notes

Version 1.13.0

XT245, XT1145, XT2145, LS4x5, HDx25, XDx35, XCx55, AU335, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes Since 1.11.1

Improvements

- BCN-13733, 13734, 14000: (XT5) XT5 players have been added to the interface so users can select them for OS updates or when creating a presentation

- BCN-14280: The position of the Assets/Widgets panel (in the Content tab) is now maintained even if the user clicks on another tab or resizes another panel

- BCN-14289: Added a splash screen to welcome users, give feedback while the application is loading, and display the version number

- BCN-14306: Changed the Schedule tab display to allow users to see the entire (24 hour) day

- BCN-14420: Updated the interface to correct the HS125 and HS145 resolution capabilities and the number of video zones in the HS145 and LS445

Bug Fixes

- BCN-12119: Ensured that the Mac version of the application will close on the first attempt

- BCN-14045: Fixed the scaling on the GPIO Output event icons

- BCN-14153: Fixed an infinite loop in the web application when uploading an empty asset

- BCN-14255: Fixed a crash that occurs when users discard unsaved presentations while trying to sign out
- BCN-14301: Fixed a bug that did not let users log in to import presentations
- BCN-14500: (HS125) Removed unsupported output resolutions