BrightSign®

OS 8.5.36 Release Notes

Affected devices:

AU3x5, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes from 8.5.33 to 8.5.36:

Improvements

OS-14731: Upgraded to latest packages per OpenSSL security advisory.

Bug Fixes

OS-13160: Fixed an issue where DHCP IP in IPv6 was bound to the DUID and not the MAC Address.

BCN-13310: Fixed support for remote directory creation.

OS 8.5.36 Release Notes 2 of 2