

May 25, 2023

BrightSign[®]

BrightAuthor Release Notes

Version 5.0.1.4

XTx45, LS4x5, HDx25, XDx35, XCx55, XTx44, XDx34, HDx24, HS1x4, LS424, XTx43, XDx33, HDx23, HO523, HS123, LS423, 4Kx42

Changes Since 5.0.1.2

New Features

- BCN-12985: Added support for the XT245, XT1145, and XT2145

Improvements

- BCN-12214: Created a WiFi “reliability mode” which allows players to automatically reconnect WiFi if it is in a bad state. If the registry key “disable_wifi_auto_recovery” is set to “true”, this feature will be disabled on the player.

Bug Fixes

- BCN-13991: Fixed a crash that occurs when sending a UDP command in a presentation that uses interactive events with Dynamic Playlist or Media List widgets.
- BCN-14596, 14571, 14461, 14247: Fixed a crash that occurs when users create sync presentations on Series 5 players.